




Assembly Instruction



Parts List:



Qty (1) Work Surface



Qty (4) Legs

Hardware Included


- (24) #12 x 1" Pan Head Wood Screws

Tools Required

- Drill with phillips screw bit

Step 1: Flip the worksurface upside down and using the (24) #12 x 1" screws, fasten the legs as shown to the premarked locations.

Assembly Instructions



Step 2: Finally, turn the table over and level the table using the adjustable glides. You are Finished!

