

# Ganging Bracket Assembly Instructions


## Components:

- Spark Ganging Brackets
- 7/8" PPH Screws

- 1 Align Ganging Bracket using peck holes in desired locations on bottom of surface.
- 2 Fasten Ganging Bracket using 7/8" PPH Screws.
- 3 Align mating Ganging Brackets on surfaces as shown.
- 4 Rotate lock mechanisms counterclockwise to lock Ganging Brackets together.



3



4

